

## **TABLE OF CONTENTS**

### **PHASE THREE: 2002-2003 ON-BOARD WARNING SYSTEMS EVALUATION**

|       |   |     |
|-------|---|-----|
| I.    | EXECUTIVE SUMMARY                                 | 1   |
| II.   | PROJECT BACKGROUND                                | 5   |
| III.  | WINTER MAINTENANCE: THE EXTREME CHALLENGE         | 8   |
| IV.   | ADVANCED SNOWPLOW RESEARCH IN ARIZONA             | 12  |
| V.    | 2002-03: YEAR FIVE – A NEW BEGINNING              | 18  |
| VI.   | EATON VORAD EVT-300 WITH SMARTCRUISE: THE SYSTEM  | 25  |
| VII.  | EVT-300: COMMISSIONING                            | 31  |
| VIII. | BENDIX XVISION INFRARED CAMERA: THE SYSTEM        | 36  |
| IX.   | XVISION: COMMISSIONING                            | 42  |
| X.    | ON-BOARD SYSTEMS: ATRC RESEARCH PLAN              | 48  |
| XI.   | ON-BOARD SYSTEMS: 2002-03 OPERATIONS              | 53  |
| XII.  | ON-BOARD SYSTEMS: ATRC RESEARCH ACTIVITY          | 59  |
| XIII. | DEFERRED RESEARCH TASKS: RESOLUTIONS              | 66  |
| XIV.  | PHASE THREE RESULTS AND CONCLUSIONS: 2002-03      | 75  |
| XV.   | ADOT ADVANCED VEHICLE RESEARCH PROGRAM: 1997–2003 | 83  |
| XVI.  | APPENDIXES  | 88  |
| XVII. | REFERENCES AND BIBLIOGRAPHY                       | 154 |

## **LIST OF APPENDIXES**

### **PHASE THREE: 2002-2003 ON-BOARD WARNING SYSTEMS EVALUATION**

|   |     |
|---|-----|
| APPENDIX A: FLAGSTAFF REGIONAL WINTER STORM HISTORY                                   | 88  |
| APPENDIX B: I-40 CORRIDOR SNOWFALL BY DATE: WINTER 2002-03                            | 91  |
| APPENDIX C: SNOWPLOW ACTIVITY BY WINTER STORM CODES: ALL SITES                        | 93  |
| APPENDIX D: SNOWPLOW ACTIVITY BY SNOWFALL DATES: ALL SITES                            | 95  |
| APPENDIX E: ADOT - ATRC DAILY ACTIVITY REPORT   | 97  |
| APPENDIX F: ADOT - ATRC INCIDENT REPORT   | 100 |
| APPENDIX G: ADOT - ATRC DRIVER SURVEYS: RADAR   | 106 |
| APPENDIX H: ADOT - ATRC DRIVER SURVEYS: NIGHT VISION                                  | 112 |
| APPENDIX I: EATON VORAD SMARTCRUISE EVALUATION REPORTS                                | 118 |
| APPENDIX J: TECHNICAL ADVISORY COMMITTEE<br>PROJECT OPINION SURVEY RESULTS: JUNE 2002 | 122 |
| APPENDIX K: ARIZONA WINTER VISIBILITY SURVEY BY ROUTE MILES: 2003                     | 133 |

## LIST OF FIGURES

### PHASE THREE: 2002-2003 ON-BOARD WARNING SYSTEMS EVALUATION

|            |   |    |
|------------|---|----|
| Figure 1:  | Winter Storms Close the Interstate 40 Corridor                  | 1  |
| Figure 2:  | Arizona's Highway Corridors are Critical to Commerce and Travel | 5  |
| Figure 3:  | Dawn Patrol on Interstate 17 in a Winter Storm                  | 8  |
| Figure 4:  | Demonstration of Caltrans-PATH Concepts: Tempe, Arizona (1997)  | 13 |
| Figure 5:  | Caltrans RoadView ASP on US 180 in Arizona                      | 14 |
| Figure 6:  | Arizona's Advanced Snowplow System: The ADOT-3M ASP             | 15 |
| Figure 7:  | Seven On-Board Systems Evaluation Routes for 2002-03            | 21 |
| Figure 8:  | EVT-300 Driver Display Module                                   | 25 |
| Figure 9:  | Caltrans RoadView Driver-Vehicle Interface Display              | 26 |
| Figure 10: | Schematic Diagram of the EVT-300 Collision Warning System       | 27 |
| Figure 11: | Driver Display Elements: EVT-300 Collision Warning System       | 28 |
| Figure 12: | EVT-300 Collision Warning Alert Sequence                        | 30 |
| Figure 13: | Radar Antenna on Bar: View of Roadway Over Snowplow Blade       | 32 |
| Figure 14: | XVision Enhancement of Reaction Time to Roadway Hazards         | 36 |
| Figure 15: | Original XVision Camera Installation on Snowplow F235           | 37 |
| Figure 16: | Original XVision Head-Up Display Unit (HUD)                     | 38 |
| Figure 17: | Bendix Upgraded Flat Screen LCD Display: Dashboard Mounting     | 39 |
| Figure 18: | XVision Thermal Imaging Display of Roadway Hazards              | 40 |
| Figure 19: | Basic XVision Mounting Exposed to Spray and Debris              | 43 |
| Figure 20: | Visor-Mounted LCD Screen for May 2002 Demo                      | 44 |
| Figure 21: | XVision Shield Added to ADOT Snowplow F235                      | 46 |
| Figure 22: | Installation of Vehicle Systems at Flagstaff Shop               | 49 |
| Figure 23: | XVision Snowplow F235 Refuels at Little Antelope Camp           | 53 |
| Figure 24: | Freeze, Thaw, and Refreeze: the Camera Window Heating Element   | 56 |
| Figure 25: | SmartCruise Antenna and Hand-Held Test Equipment                | 68 |
| Figure 26: | Gray Mountain and Kingman Plows: ADOT Equipment Rodeo           | 69 |
| Figure 27: | Chambers and Winslow Plows: Four Corners Conference             | 70 |
| Figure 28: | Impaired Visibility Snowplow Routes                             | 74 |
| Figure 29: | An Early Winter Storm Slows I-17 Traffic                        | 75 |
| Figure 30: | Monroe Prototype Camera Lens Washer System                      | 78 |
| Figure 31: | Storm Cleanup: An Icy Highway in Northern Arizona               | 85 |

## LIST OF TABLES

|           |   |    |
|-----------|---|----|
| Table 1:  | Arizona "Snowy-and-Icy" Roadway Crashes: Calendar Year 2002 | 9  |
| Table 2:  | Wintry Conditions in Crashes: Calendar Year 2002            | 10 |
| Table 3:  | Arizona Snowplow Accident Repairs by Winter Season          | 11 |
| Table 4:  | Route Assignments of Project Snowplows: Year Five           | 22 |
| Table 5:  | ADOT Winter Storm Activity With EVT-300 CWS Radar           | 34 |
| Table 6:  | ADOT Winter Storm Activity With Bendix XVision              | 47 |
| Table 7:  | Phase Three Activity Summary for Seven Research Snowplows   | 54 |
| Table 8:  | NWS Weather Observation Stations for Project Plow Routes    | 64 |
| Table 9:  | Final Results of the Statewide Winter Visibility Survey     | 72 |
| Table 10: | Flagstaff Winter Storm Summary: 1997-2003                   | 83 |
| Table 11: | Arizona "Snowy and Icy" Crash Records: Six Winters          | 84 |